

# Toyota A750E/F (RWD/AWD 5-Spd)

ILL NO.	PART NUMBER	PER UNIT	DESCRIPTION	YEARS
<b>REBUILDER BOX KITS</b>				
---	K7200M-S 1	1	Master Kit (w/o Steels)	2003-15
---	K7200M-9	1	Steel Plate Kit	2003-15
1 For 2003-07 Landcruiser & LX470, please order 72553B Adaptor Seal separately. <b>Not in kit.</b>				
<b>OVERHAUL KITS, GASKET SETS, AND SEAL KITS</b>				
---	K72900M 1		Overhaul Kit	A750E/F 2003-15
---	K72900M-3		Valve Body Gasket Set	A750E/F 2003-15
1 For 2003-07 Landcruiser & LX470, please order 72553B Adaptor Seal separately. <b>Not in kit.</b>				
<b>GASKET AND RUBBER COMPONENTS</b>				
1F	72170M	1	Oil Pan Gasket	2003-15
3A	72100M	1	Front Pump Body to Pump Cover O'Ring	2003-15
4A	72101M	1	Front Pump to Case O'Ring	2003-15
<b>METAL CLAD SEALS</b>				
10A	67526V	1	Front Pump (Viton)	2003-15
11C	72551	1	Extension Housing (40x58x11mm)	A750E (2WD) 2003-15
---	72553M	1	Adapter Housing (43x58x8mm)	Except Below 2003-15
---	72553B	1	Adapter Housing (48x62x10mm)	LX470 & Landcruiser 2003-07
---	74552	1	Adapter Housing (51x66x6.5mm)	Sequoia 08-09, Tundra 07-09 2007-09
12E	68504	2	Manual Lever	2003-15
<b>TRANSMISSION OIL FILTERS</b>				
75F	72600M	1	Oil Filter	2003-15
See Catalog Page 13.27-1 for Visual Filter Identification.				
<b>SEALING RINGS</b>				
---	K72901M	1	Sealing Ring Kit	2003-15
<b>CLUTCH PLATES</b>				
20A	72302M	5-6	C2 (Direct) Friction	36 Teeth, .059" - 6.370" O.D. 2003-15
21A	72303M	5-6	C2 (Direct) Steel	24 Teeth, .071" - 5.866" I.D. 2003-15
27B	72304M	6-7	C1 (Forward) Friction	30 Teeth, .075" - 4.705" O.D. 2003-15
28B	72305M	5-6	C1 (Forward) Steel	24 Teeth, .071" - 4.173" I.D. 2003-15
31B	72306M	5	C3 (Reverse) Friction	40 Teeth, .059" - 6.370" O.D. 2003-15
32B	72303MA	4	C3 (Reverse) Steel	24 Teeth, .094" - 5.866" I.D. 2003-15
35C	72308M	4	B3 (2nd Brake) Friction	40 Teeth, .072" - 6.437" O.D. 2003-15
36C	72309N	4	B3 (2nd Brake) Steel	16 Teeth, .079" - 5.197" I.D. 2003-15
38D	72300M	3-4	B1 Friction	40 Teeth, .072" - 6.229" O.D. 2003-15
39D	72301M	3-4	B1 Steel	13 Teeth, .094" - 5.528" I.D. 2003-15
41D	72312M	3	B2 (2nd Coast) Friction	40 Teeth, .061" - 5.442" OD 2003-15
42D	72313M	3	B2 (2nd Coast) Steel	13 Teeth, .079" - 4.538" ID 2003-15
45E	72321N	8	B4 (Low/Reverse) Friction	48 Teeth, .061" - 5.527" OD 2003-15
46E	72322M	7	B4 (Low/Reverse) Steel	16 Teeth, .071" - 4.921" ID 2003-15
---	K7200M-F	1	Friction Module	2003-15
---	K7200MHP-F	1	Friction Module (Alto HP Red)	2003-15
---	K7200MHP-9	1	Steel Module (Kolene)	2003-15
<b>BUSHINGS</b>				
---	K72980MDB	1	Bushing Assortment Kit (DuraBond)	2003-15
50A	67005	1	Front Pump	2003-15
---	67002C	1	Stator, Front	2003-15
60C	72008C	1	Extension Housing	2003-15

# Toyota A750E/F (RWD/AWD 5-Spd)

ILL NO.	PART NUMBER	PER UNIT	DESCRIPTION	YEARS
<b>MOLDED RUBBER PISTONS</b>				
84A	72847M	1	C2 Clutch Balance Piston (Molded Rubber)	2003-15
<b>SHIFT ENHANCEMENTS AND VALVES</b>				
---	A750E-A761E-ZIP	1	Zip-Kit (Sonnax)	2003-15
---	K72944MRT	1	Valve Body Kit (RatioTek)	2003-15
---	K72944MHD	1	Valve Body Kit (RatioTek)	2003-15
---	K72944MU	1	Shift Kit (TransGo, Updated w/TCC Relay Fix- with Reamer - Repairs 1 Unit)	2003-15
---	K72944MU-RF	1	Valve Refill Kit for K72944MU (TransGo, No Reamer - Repairs 1 Unit)	2003-15
			Addresses: Worn Valve Body Bores that sets TCC Codes, 2-3 Flare and Rough Kickdown.	2003-15
---	K72889M	1	Boost Valve Assembly (Anodized Aluminum)	2003-15
---	K72889MTG	1	Boost Valve Assembly (Hardened Steel)	2003-15
---	K72889MLB	1	Line Pressure Booster Kit (Sonnax)	2003-15
---	K72887M	1	Lock-Up Control Plunger Valve and Sleeve Kit (Sonnax, RPM Surge)	2003-15
---	K72881M	1	Accumulator Control Plunger Valve and Sleeve (Sonnax, Harsh Shifts & Codes)	2003-15
---	K72788M	1	O'Ringed End Plug Kit (Sonnax, Pressure Loss)	2003-15
---	K14780	1	B1 Accumulator Piston Kit w/Sealing Ring (In VB)	2003-15
---	K14780W	1	B1 Accumulator Piston Kit w/O-Ring (In VB)	2003-15
---	K72883M	1	B1 Apply Control Plunger Kit	2003-15
<b>ELECTRONIC COMPONENTS</b>				
90F	72871M	1	Shift Solenoid 1 "A" (On/Off)	2003-15
91F	72872M	1	Shift Solenoid 2 "B" (On/Off)	2003-15
92F	72873M	1	SL1 Solenoid (Pressure Control A) (PWM)	2003-05
92F	72873N	1	SL1 Solenoid (Pressure Control A) (PWM)	2004-15
93F	72873MA	1	SL2 Solenoid (Pressure Control B) (PWM)	2003-05
93F	72873N	1	SL2 Solenoid (Pressure Control B) (PWM)	2004-15
94F	72874M	1	SR Solenoid (Shift E) (On-Off)	2003-15
95F	72870M	1	SLU Solenoid (TCC) (PWM)	2003-05
95F	72870N	1	SLU Solenoid (TCC) (PWM)	2004-15
96F	72879M	1	SLT Solenoid (EPC) (PWM)	2003-05
96F	72879N	1	SLT Solenoid (EPC) (PWM)	2004-15
100D	72869M	1	Internal Wiring Harness and Temp Sensors	2003-05
100D	72869MA	1	Internal Wiring Harness and Temp Sensors	2004-15
100D	K72859MVC	1	External Harness Repair Kit	2003-15
101C	72875M	1	Input Speed Sensor	2003-15
102C	72875M	1	Output Speed Sensor	2003-15
113D	72877M	1	Neutral Safety Switch (7-Pin, 2-Blade Connector)	2003-On
<b>Hard Parts</b>				
---	K72895M	1	Front Pump Assmebly	2003-15
150F	70-118LA	1	Reman Valve Body (Large Body Solenoids, w/Relay Valve)	2003-05
150F	70-118LB	1	Reman Valve Body (Large Body Solenoids, w/o Relay Valve)	2003-05
150F	70-118SA	1	Reman Valve Body (Small Body Solenoids, Casting # 8850, w/Relay Valve)	2004-15
150F	70-118SB	1	Reman Valve Body (Small Body Solenoids, Casting # 8850, w/o Relay Valve)	2004-15
150F	70-118SC	1	Reman Valve Body (Small Body Solenoids, Casting # 89010, w/Relay Valve)	2004-15
150F	70-118SD	1	Reman Valve Body (Small Body Solenoids, Casting # 89010, w/o Relay Valve)	2004-15